

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

MICHAEL O. LEAVITT Governor

OLENE S. WALKER Lieutenant Governor

Representativ	Representatives Present During the Inspection		
 Company	James Byars	_	
OGM	Joe Helfrich Reclamation Specialist III		

Inspection Report

Permit Number:	C0150007		
Inspection Type:	COMPLETE		
Inspection Date:	Wednesday, September 24, 2003		
Start Date/Time:	09/24/2003 9:00:00 AM		
End Date/Time:	09/24/2003 2:00:00 PM		
Last Inspection:	Wednesday, August 20, 2003		

Inspector: Joe Helfrich, Reclamation Specialist III

Weather: sunny 85

Accepted by: dhaddock 10/07/2003

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Site: HIDDEN VALLEY MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

0......

Current A	Acreages	Mineral Ownership	Types of Operations		
960.00	Total Permitted	☐ Federal	☐ Underground		
6.70	Total Disturbed	☐ State	☐ Surface		
6.70	Phase I	\Box County	Loadout		
	Phase II	☐ Fee	☐ Processing		
	Phase III	Other	Reprocessing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

The purpose of this visit was to conduct a complete inspection of the Hidden Valley site.

Inspector's Signature:	Da	ate	Thursday, September 25, 2003

Joe Helfrich, Reclamation Specialist III

Inspector ID Number: 1



Permit Number: C0150007 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 24, 2003

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	~		✓	
3.	Topsoil	~			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓			
4.c	Hydrologic Balance: Other Sediment Control Measures	~		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓			
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches	✓			
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	~			
10.	Slides and Other Damage	~			
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading	~			
13.	Revegetation	~		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.	a Roads: Construction, Maintenance, Surfacing	✓			
16.	b Roads: Drainage Controls	✓		✓	
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance	✓		✓	
22.	Other				

Permit Number: C0150007 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 24, 2003 Page 3 of 3

1. Permits, Change, Transfer, Renewal, Sale

The reclamation permit was renewed on January 29, 2002 and expires January 30, 2007. On September 19, 2003 the Division received an application for a permit transfer from Consolidation Coal Company to C&P Coal Corp pending the sale of the Hidden Valley mine. The sale is anticipated to close no sooner than November, 14, 2003.

2. Signs and Markers

A sign containing the required information was posted at the entrance to the access road.

4.c Hydrologic Balance: Other Sediment Control Measures

Water was flowing in Ivie Creek at 2 GPM. The silt fences were in good repair.

4.d Hydrologic Balance: Water Monitoring

The MRP requires sampling Ivie Creek above and below the mine in the spring and fall or high and low water. Sample and field measurements were scheduled to be taken on taken on September 19, 2003.

13. Revegetation

As of the date of this inspection, the grasses forbes and shrubs were doing well in spite of this year's drought.

16.b Roads: Drainage Controls

As of the date of this inspection, the water bars along the road were in good repair.

21. Bonding and Insurance

Insurance was renewed and is effective from November 5, 2002 to November 5, 2003. The surety bond is on record for \$90,758 and is effective for the permit period. The rider is dated January 8, 1997.